


# Unit 2: Water Audit Results

## Detailed bathroom maps with location of leaky toilets


### Griffen

8th Floor Mix Gender




Toilet T3 is leaking and need new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

7th floor mix gender




All Toilets working properly  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

6th Floor mix gender




All Toilets working properly  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

5th floor mix gender




All Toilets working properly  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

4th Floor mix gender




Toilet T1 is leaking and needs new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

3rd floor mix gender




Toilet T1 is leaking and needs new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

2nd Floor, mix gender




All Toilets working properly  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

1st floor mix gender




Toilet T2 is leaking and needs new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

ground floor bathrooms not tested




# Cunningham

8th Floor Mix Gender




Toilet T1, T2 and T3 are leaking and need new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

7th floor mix gender




Toilet T1 and T3 are leaking and need new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

6th Floor mix gender




Toilet T1 and T3 are leaking and need new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

5th floor mix gender




Toilet T3 is leaking and needs new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

4th Floor mix gender




Toilet T1 is leaking and needs new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

3rd floor mix gender




All Toilets working properly  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

2nd Floor, mix gender




Toilet T3 is leaking and needs new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

1st floor mix gender




Toilet T3 is leaking and needs new flush value kits  
Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

ground floor bathrooms not tested




# Ehrman

8th Floor Mix Gender




Toilet T3 is leaking and needs a new flush value kits  
 Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

7th floor mix gender




Toilet T1 is leaking and needs a new flush value kits  
 Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

6th Floor mix gender




Toilet T1 is leaking and needs new flush value kits  
 Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

5th floor mix gender




All Toilets working properly  
 Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

4th Floor mix gender




Toilet T2 and T3 are leaking and need new flush value kits  
 Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

3rd floor mix gender




Toilet T3 is leaking and needs new flush value kits  
 Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

2nd Floor, mix gender




Toilet T1, T2 and T4 are leaking and need new flush value kits  
 Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

1st floor mix gender




All Toilets working properly  
 Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

ground floor bathrooms not tested



## Davidson


Davidson 8th Floor



All toilets working properly

Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount


Davidson 7th floor



Toilet 3 needs new flush kit or screw needs to be adjusted

Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount


Davidson 6th Floor



Toilets T1 and T2 need new flush Kits or screw needs to be adjusted


Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

Davidson 5th floor



Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount


Davidson 4th floor



Toilets T1, T3 and T4 need new flush Kits or screw needs to be adjusted

Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount


Davidson 3th floor



All Toilets working property


Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

Davidson 2nd floor



Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

Davidson first floor



Toilet1 needs new flush kit or screw needs adjustment

Toilets: Sloan LC USA, 1.6gallons/flush bowl, wall mount

ground floo I male, I female bathroom

male = 5 sec

put 0.5 low-flow aerator in it